



Technical Support

Article Index

Updated - 29th June 2015

Tech Note #	Description	Category
00001-2010	USB Adaptor Drivers	AIS+USB
00002-2010	WL50 (MK2) or WL400 on Snow Leopard	Wi-Fi
00003-2010	SOB and Windows 7	Software
00004-2010	Sharing Internet on Mac	Wi-Fi
00005-2010	NMEA data detected as Mouse	PC
00006-2010	Opening Charts on SmarterTrack	Software
00007-2010	Aqua Media no VGA	PC
00008-2010	AIS200 to Lowrance HDS5+7	AIS
00009-2010	WL50+WL500 Adaptor Drivers	Wi-Fi
00010-2010	WL400 Adaptor Drivers	Wi-Fi
00011-2011	Fault finding Class B Transponders	AIS
00012-2010	Kaspersky inhibiting Wifi Adaptors	Wi-Fi
00013-2010	Setting up NMEA to USB on a Mac	AIS+USB
00014-2010	Using AIT1000 with MacENC on a Mac	AIS
00015-2010	Changing NMEA to USB COM Port allocation	AIS+USB
00016-2011	Connecting an AIS to a Raymarine C Series	AIS
00017-2011	Connecting an AIS to Standard Horizon Plotters	AIS
00018-2011	Connecting an AIS to Garmin 400/500 Plotters	AIS
00019-2011	Using an LED to test NMEA0183 output	NMEA0183
00020-2011	WL50 Mk2 Adaptor Drivers	Wi-Fi
00021-2011	Upgrading from iAIS to iNavX	AIS
00022-2011	Fault Finding AIS200 range on a PC	AIS
00023-2011	Configuring WLN10 Baud Rate	Wi-Fi
00024-2011	Software Updating an AIS Receiver Board	AIS
00025-2011	Diagnosing Class B Transponder Alarms	AIS
00026-2011	How to fix an AIT1000 Software Upgrade Failure	AIS
00027-2011	WL510 cannot log on to some Hotspots	Wi-Fi
00028-2011	WL510 Firmware Update Procedure	Wi-Fi
00029-2011	WL50+WL400 on Lion OSX for Macs	Wi-Fi
00030-2012	Multiple Connections on Wireless NMEA products	Wi-Fi
00031-2012	iNavConnect Firmware Update	Wi-Fi
00032-2012	Configuring an AIT2000 on a Mac using proAIS2	AIS
00033-2012	Using AIT2000 with MacENC on a Mac	AIS
00034-2012	Problems installing proAIS2 drivers on Vista and 7	AIS



Tech Note #	Description	Category
00035-2012	Using AIS with OpenCPN	AIS
00036-2012	Fault Finding AIT2000 Transponders	AIS
00037-2012	iNavConnect and Raymarine Networks	Wi-Fi
00038-2012	Changing iNavConnect SSID and Password	Wi-Fi
00039-2013	Using WL510 with iNavConnect	Wi-Fi
00040-2012	Using a Mac with the WL510	Wi-Fi
00041-2012	Re-Configuring an HSC100	Sensors
00042-2013	Using WL510 with iNavHub	Wi-Fi
00043-2012	Firmware Update for AIT2000/CLB2000/AIS200N2Net	AIS
00044-2012	Using an AIT2000 with OpenCPN on a Mac or LINUX PC	AIS
00045-2012	Discovering and Resetting a WL510	Wi-Fi
00046-2012	Using Wireless Products on Existing Network	Wi-Fi
00047-2012	RF Connector Types Explained	General
00048-2013	Updating iAIS Firmware for AP Mode	Wi-Fi
00049-2013	Using a Fusion 700 Series with iNavConnect	Wi-Fi
00050-2013	Changing iNavHub SSID and Password	Wi-Fi
00051-2013	Updating WLN10+WLN10HS Firmware for AP Mode	Wi-Fi
00052-2013	Using an AIT2000 with Standard Horizon GX2000 VHF	AIS
00053-2013	Configuring Wi-Fi Products for Wireless+3G connections	Wi-Fi
00054-2014	Connecting GPS data to Icom Radios	GPS
00055-2014	Connecting GPS data to Standard Horizon Radios	GPS
00056-2014	Dual Input Wireless NMEA with MUX100 and WLN10HS	Wi-Fi
00057-2014	Sharing Internet on a PC or a Mac (WL60/Wi-Connect)	Wi-Fi
00058-2014	AIS to Navico Plotters	AIS
00059-2014	Configure AIT2000 to drive Autopilot from iNavX	AIS + Wi-Fi
00060-2014	Using Navionics Charts with SmarterTrack 2014	Software
00061-2014	Using USB Products with OpenCPN V3.2 or higher	Software
00062-2014	Using Wi-Fi Products with OpenCPN V3.2 or higher	Software
00063-2015	Config Transponder for Single NMEA Port MFD	AIS
00064-2015	AIT2000+AIT3000 Inhibit NMEA2000 GPS data	AIS
00065-2016	Change IP address on our Wi-Fi Gateways	Wi-Fi